

Trig_Ctrl are signals sent
along the user defined pins
of P2 for Global signals
sent throughout the trigger.
NOTE: Be sure to buffer
any P2 signals going to more than
one chip on the board, so that
the tracer doesnt get overloaded.

DATE	REVISION DESCRIPTION
1998-12-17	Modified from PreFRED 2 VME Interface

UNIVERSITY OF CHICAGO
ELECTRONICS DEVELOPMENT GROUP

TITLE
Hit Finder / VME Interface

SHEET 3 OF 20
DATE 1998-12-17
DRWN WJA/MAB

C-2421
REV A